

Annexure D

BUILDING SAFETY CERTIFICATE

No. 778/SD/VP

Dated: 03-01-2025

It is certified that the existing building St. Mary's Convent High School (name of the building or premises) at Smeilpur, Bari - Brahmana, Dist. Samba (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	03	03	-	-	-	-

The building is owned/occupied by St. Mary's Convent High School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Public Works Dept. (Name of Department/ Govt.) on 23-12-2024 (date of inspection) in the presence of Cherk (Lokesh) representative (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 01-01-2025 for a period of years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Nothing extra-ordinary/natural calamity happens.
2. Any additional alteration carried out to be brought to the notice of undersigned.
3. Timely repairs to be carried out as and when required.
4. This certificate is not valid for legal / court purpose.

Issued on 01-01-2025 at Vijaypur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Name

Designation

Name & Address of Department/ Office: PND SD vijaypur